

CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 11

ISSUED TO: All Cosalt Service Stations

DATE: February 2005

SUBJECT: Pressure Relief Valve on
Cosalt Elite Lifejacket



The Pressure Relief Valve on the Cosalt Elite Twin Chamber Lifejacket is fitted with a rubber 'O' ring seal. We have had a report of a small number of lifejackets where this 'O' ring has shown signs of cracking and perishing.

We therefore recommend that this 'O' ring should be checked when you are servicing the Cosalt Elite Lifejacket. If there are any signs of deterioration the 'O' ring should be replaced, even if it is not causing the Relief Valve to leak. Please note that this refers to the Cosalt version of the Elite Lifejacket only.

This recommendation will be included in the next issue of the Elite Lifejacket Service Manual.

Norman Kitching
Crewsaver
QA Manager