

CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 43


Issued to: GAO, CGG
DATE ISSUED: 3rd January 2014
SUBJECT: Crewfit Twin 2010 with Cowtail
ISSUED BY: Carol Champney
EXP DATE: Not Applicable

Changes from previous issue:

Please be advised that the threading of the cowtail on the 2010 Crewfit twin 1174-23 and 1174-24 has not been passed through the belt.



INCORRECT
 The images are showing the cowtail only attached to the cowtail retainer



CORRECT
 The images show the cowtail attached to the belt and the cowtail retainer

To rework. Unthread the belt pass through the cowtail re thread the belt.