

CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 8



Crewsaver

ISSUED TO: All Approved Service Stations

DATE: 18th December 2003

SUBJECT: Crewfit Twin Chamber Lifejacket
with Integral Deck Safety Harness

It has come to our attention that, due to a manufacturing error, part of the back strap is missing on the Crewfit Twin Chamber lifejacket with integral Deck Safety Harness. A relatively small number of this particular lifejacket have been produced and we are contacting all the people we have supplied them to.

Should you receive one of these lifejackets for servicing can you please check whether there is a central backstrap connecting the waistbelt to the cover at the back of the neck. If this strap is missing the jacket should be returned to us for modification. If you are in any doubt please contact the undersigned.

Please note that this notice refers to the Crewfit Twin with an integral Crewsaver Deck Safety Harness only. It does not refer to the Crewfit Twin fitted with a Fall Arrest Harness such as the BH Sala N300.

Norman Kitching
Crewsaver
QA Manager