

CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 10




ISSUED TO: All holders of Care & Maintenance Certificates for Crewfit 150N, Crewfit 275N, Seafire Solas and Elite Lifejackets.

DATE: January 2005

SUBJECT: Fitting of Sealing Washer to Mk. 3 Automatic Operating Head

This bulletin concerns all users of Crewsaver automatic lifejackets fitted with a United Moulders Mk.3 automatic operating head, as illustrated below, and purchased before 1998. The particular lifejackets involved are the Crewfit 150N, Crewfit 275N, Seafire Solas and Elite.



As part of our continuing policy of controlling quality it has been found that, over time, in exceptional circumstances, the repeated over-tightening of the CO₂ gas cylinder may cause wear within the moulding of the operating head. This can result in gas escaping when the jacket is inflated and the lifejackets listed above may need a minor modification to ensure their continued safe operation.

The modification is simple and can be carried out by the owner of the lifejacket. If your lifejacket is one of those listed above, please contact us and we will send you a modification kit which will contain full instructions.

Norman Kitching
Crewsaver
QA Manager