

TO: All holders of Seafire Solas
Servicing Certificates.
All Service Stations.
All Environment Agency
Regional H & S Advisers.

SERVICING BULLETIN No. 1

Seafire Solas Twin Chamber Lifejacket

It has come to our attention that there may be instances where the belt and buckle of the Seafire Solas Lifejacket are not being checked in accordance with the servicing procedure.

All Seafire Solas Lifejackets should be checked as per section 3.2 of the Servicing Manual:

“Check the function of the One Piece ‘Thread Through’ Buckle by threading the webbing through in the correct sequence. The webbing can be pulled through the buckle to tighten the belt but cannot be pulled back due to the self-locking nature of the buckle.”

Please ensure that the above procedure is carried out when servicing Seafire Solas Lifejackets. Any lifejackets currently in your possession should be checked immediately. If a fault is found with the buckle the jacket should be returned to Crewsaver for correction.

Norman Kitching,
Quality Assurance Manager.

16th February 2001