

## CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 42

**Issued to:** All Service Stations  
**DATE ISSUED:** 20<sup>th</sup> December 2013  
**SUBJECT:** VML MK5i Auto Capsule Black  
**ISSUED BY:** Carol Champney  
**EXP DATE:** Not Applicable

Changes from previous issue: 2

**Batch No: 11 – 2016C**  
**Part No: R17003**

We have been advised by our supplier United Moulders Ltd, that there may be extra sensitive capsules, which will result in inadvertent dry firing. This problem is due to an intermittent moulding issue and is batch related.

All capsules from the above batch No: are to be returned to Crewsaver. Please email quantities prior to returning so free of charge replacements can be sent out.

Email: [carol.champney@survitecgroup.com](mailto:carol.champney@survitecgroup.com)

We thank you for your attention.

Best Regards  
Carol Champney

Quality Manager

