

## SSD T/A CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 50


**ISSUED TO:** RNLI  
**DATE ISSUED:** August 2015  
**SUBJECT:** Change of Lifejacket Light  
**ISSUED BY:** Guy Page  
**EXP DATE:** N/A

---

There has been a change to the Crewsaver CSL Lifejacket Light fitted to the RNLI Lifejackets. The difference is in the type of sensor fitted to the light, as shown below.



New style sensor



Old style sensor

The lamp unit is fitted to the jacket in exactly the same way as the old style of light. The sensor unit is secured by fastening the light retaining velcro at the back of the inflation chamber around the light cord.

The light can be tested by pressing firmly on the circular marked area of the sensor unit.