

Survitec Service & Distribution Ltd (Crewsaver)

---

**Servicing / Technical bulletin number: 069**

**Issued to:** Service Network (PAL /Pas Approved sites)

**Date Issued:** Sept 2021

**Subject:** Extended service program on PAL/PAS “Hermetic seals”.

**Issued by:** Guy Page (Technical)

**Exp date:** April 2022


---

## Extended service program on PAL/PAS “Hermetic seals”

To help improve and ensure the safety of Personnel during this outbreak of COVID 19, there has been an extension to the service program until April 2022 on PAL/PAS Hermetic seals.

To adhere to this extension the following must be met: -

- All products must be inspected before operational use. The hermetic sealed bag must be fully in tacked/sealed.



- Sealed product will show no sign of movement withing the Hermetic bag. (Image 1)
- If the seal has broken, you will find that the corners of the bag will release, and the product will be able to move around in the bag. (Image 2)
- Any damage product Must be removed from service and undergo service as to the service manual.

Survitec Service & Distribution Ltd (Crewsaver)

---

- Any jacket which shows signs of an issues with the hermetic seal must be recorded. (including the following information)
  - A photograph of the bag and where the seal has been broken.
  - Record the dates of service.
  - Serial number
  - This data must be return to Crewsaver  
(Email [Guy.page@survitecgroup.com](mailto:Guy.page@survitecgroup.com) and [zach.williams@survitecgroup.com](mailto:zach.williams@survitecgroup.com))

This Extended service program is in place on agreement with both Crewsaver and RFD (Australia) Pty. Ltd and will Expire at the end of April 2022, when all products must have been serviced.

If you have any questions, please contact: -

Guy Page  
Training and Technical Support Manager,  
Survitec Group  
[guy.page@survitecgroup.com](mailto:guy.page@survitecgroup.com)

**Note: - Only PAL/PAS approved sites may service this Product.**