

## CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 7



**ISSUED TO:** All holders of Service Manuals  
for the Crewfit Twin Chamber  
Lifejacket.

**DATE:** 4<sup>th</sup> September 2003

**SUBJECT:** Replacement Hammar Auto Heads.

**Crewsaver**

The current Issue of the Service Manual for the Crewfit Twin Lifejacket (Issue 5, dated April 2002) says that the lifejacket should be re-armed using a Hammar auto cap **with an extended lanyard**.

Please note that this applies only to jackets manufactured from December 1998 onwards. Jackets manufactured before that date should be re-armed using a **normal** Hammar auto cap as the hole where the cap is fitted is in a slightly different position.

The date of manufacture of any particular lifejacket can be determined by reference to the Instruction label or the Service label attached to the jacket. The first part of the Serial Number shows the month and year of manufacture.

Norman Kitching  
Crewsaver  
QA Manager