

**CREWSAVER SERVICING AND
MAINTENANCE BULLETIN No. 4**

ISSUED TO: Approved Service Stations and
 Servicing Personnel with responsibility
 for Hammar Inflators.

DATE: 2nd August 2002

SUBJECT: Revised Service Instructions
 issued by C.M. Hammar.

Hammar has issued the enclosed Production & Servicing Assembly instructions. Please read all of these instructions. We would draw your attention to Section 3 which gives various methods for tightening the gas cylinder into the inner body. Hammar recommend that Section 3C should be used "for heavy users and/or extreme working conditions". Since you will not necessarily know whether your customers come into this category, Crewsaver recommend Option 3C (the use of Loctite 222) as the preferred method in all cases. This option has the added benefit that tightening with a torque wrench is not required.

The bench mounted bracket and the cylinder adaptor tool are available from Crewsaver as are further copies of the instructions. The torque wrench and the Loctite will have to be purchased locally.

Norman Kitching
Crewsaver
QA Manager