

SSD T/A CREWSAVER SERVICING AND MAINTENANCE BULLETIN No. 49

ISSUED TO: All Service Stations and RNLI


DATE ISSUED: February 2015

SUBJECT: Change of retaining clip on Halkey Roberts Manual Head

ISSUED BY: Scott Sanders

EXP DATE: N/A

There has been a change in the Retaining Clip fitted to the Halkey Roberts Manual Firing Head – Sales Part No. 10210. The new type clip is smaller than the existing clip, as shown in the illustration below.



Supplies of the existing clip held by Service Stations can still be used but when future orders are placed for Part No. 10210 the new type clip will be supplied.