

**CREWSAVER SERVICING AND  
MAINTENANCE BULLETIN      No. 5**

**ISSUED TO:**            Environment Agency personnel  
involved with the Care and  
Maintenance of Crewsaver  
Lif jackets and Buoyancy Aids.

**DATE:**                    22<sup>nd</sup> July 2003

**SUBJECT:**                Repacking of Environment Agency Bailiff and  
Corporate Waistcoats.

Great care should be taken when repacking the Bailiff and Corporate Waistcoats after use. It is very important to ensure that the yellow inflation chamber is not twisted in any way, as this will prevent the jacket from operating properly the next time it is used.

After the jacket has been re-armed it should be laid flat on a table or desk. Make sure that the firing head with the cylinder and capsule is uppermost on the right hand side and that the mouth inflation tube is uppermost on the left hand side. Slide your hands along both sides of the inflation chamber towards the neck to ensure that there are no twists in the inflator.

Pass the manual inflation lanyard through the slot in the outer cover. Fold both sides of the inflation chamber over, from the zip to the outer edge, then fasten the touch and close fastening on each side. Turn the jacket over and, making sure that the neck of the inflation chamber is flat, fasten the studs of the back flap.

Norman Kitching  
Crewsaver  
QA Manager